Seascape Body and Tube Slide Refurbishment 2/12/2019			
	IPS Waterslide, Inc.	Safe Slide Restoration	SlidePros
BID BOND	Х	Х	Х
SCOPE OF WORK			
TUBE SLIDE			
Tube Slide Interior Resurface	\$12,500.00	\$54,355.20	\$18,465.00
Tube Slide Exterior Resurface	\$10,000.00	\$13,873.80	\$15,015.00
	BODY SLIDE		
Body Slide Interior Resurface	\$9,500.00	\$30,894.00	\$11,020.00
Body Slide Exterior Resurface	\$8,500.00	\$7,934.40	\$8,920.00
ALTERNATE #1			
Repair fiberglass at 8" supply pipe connection (body slide)	\$2,750.00	\$3,471.30	\$1,780.00
Repair fiberglass at 12" supply pipe connection (tube slide)	\$2,750.00	\$3,471.30	\$1,780.00
GRAND TOTAL W/ ALTERNATE	\$46,000.00	\$114,000.00	\$56,980.00